

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 0 8 1 2 8 2 8 0 9 0 3 8 2 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 0230 hours, August 12, 1982, during routine surveillance, the Control Room Operator  
0 3 received indication of low service water flow on No. 25 Containment Fan Coil Unit  
0 4 (CFCU). No. 25 CFCU was declared inoperable and Action Statement 3.6.2.3a was  
0 5 entered at 0230 hours, August 12, 1982.

0 6  
0 7  
0 8

0 9 SYSTEM CODE S B 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 18 19 20  
17 LER RO REPORT NUMBER 8 2 0 8 3 0 3 L 0  
21 22 23 24 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
X 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 9 26  
33 34 35 36 37 40 41 42 43 44 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this occurrence was a ground in the 28 volt system which prevented the  
1 1 proper signal from reaching No. 25 Containment Fan Coil Unit (CFCU) Flow Control  
1 2 Valve Positioner. The ground was cleared and No. 25 CFCU tested satisfactorily.  
1 3 No. 25 CFCU was declared operable and Action Statement 3.6.2.3a was terminated at 1520  
1 4 hours, August 12, 1982.

1 5 FACILITY STATUS E 28 % POWER 0 8 2 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Testing 32  
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT Z 33 Z 34 NA AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 80

2 0 PUBLICITY ISSUED DESCRIPTION NA 45 8209160198 820903 PDR ADDCK 05000311 S PDR  
7 8 9 10 68 69 80

NAME OF PREPARER

R. Heller

PHONE:

609/935-6000 Ext. 3078

NRC USE ONLY