

CONTROL BLOCK:

--	--	--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	7	2	7	0	8	1	1	8	2	8	0	8	2	5	8	2	9
60	61									68	69						74	75						80

DOCKET NUMBER

EVENT DATE

REPORT DATE

0 2 | On August 11, 1982, during routine operation, the Control Operator noticed that
0 3 | service water flow indication for No. 13 Containment Fan Coil Unit (CFCU) was
0 4 | erratic. The unit was declared inoperable and Action Statement 3.6.2.3.a was
0 5 | entered. Because redundant cooling capability was provided by the containment
0 6 | spray systems, no risk to the public was involved. The occurrence constituted
0 7 | operation in a degraded mode in accordance with Technical Specification 6.9.1.9.b.
0 8 | (81-099, 81-086, 81-075, 81-071, 80-023)

SYSTEM CODE S B 11		CAUSE CODE C 12		CAUSE SUBCODE Z 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE T 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 2 21 22		SEQUENTIAL REPORT NO. 0 6 1 24 25 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32									
ACTION TAKEN X 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 38 39 40		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER F 1 2 0 26 44 45 46 47	

1 0 The erratic flow indication was due to silt plugging the high side sensing line of

1 1 the outlet flow transmitter. The sensing lines were blown down, and the trans-

1 2 mitter was returned to service. The CFCU was declared operable and the action

1 3 statement terminated.

7	8	9							80							
FACILITY STATUS			% POWER			OTHER STATUS (30)			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION (32)			80	
1	5	E	(28)	0	5	5	(29)	N/A	A	(31)	Operator Observation				80	
7	8	9	ACTIVITY CONTENT			AMOUNT OF ACTIVITY (35)			LOCATION OF RELEASE (36)						80	
RELEASED OF RELEASE															80	
1	6	Z	(33)	Z	(34)	N/A			N/A						80	
7	8	9	PERSONNEL EXPOSURES												80	
NUMBER			TYPE			DESCRIPTION (39)									80	
1	7	0	0	0	(37)	Z	(38)	N/A							80	
7	8	9	PERSONNEL INJURIES												80	
NUMBER			DESCRIPTION (41)												80	
1	8	0	0	0	(40)	N/A									80	
7	8	9	LOSS OF OR DAMAGE TO FACILITY			(43)									80	
TYPE			DESCRIPTION												80	
1	9	Z	(42)	N/A												80
7	8	9	PUBLICITY												80	
ISSUED			DESCRIPTION (45)												80	
2	0	N	(44)	N/A												80
7	8	9													80	

NRC USE ONLY
 8209160258 820825
 PDR ADOCK 05000272
 S PDR

PHONE: (609) 541-5900 629