

## LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 0 8 3 0 8 2 8 0 9 0 3 8 2 9  
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1100 hours, August 30, 1982, an operator discovered a service water leak from  
03 No. 23 Containment Fan Coil Unit (CFCU). No. 23 CFCU was declared inoperable and  
04 isolated. Because No. 24 CFCU was already inoperable, Action Statement 3.6.2.3b was  
05 entered at 1100 hours. In accordance with NRC Bulletin 80-24, the NRC was notified  
06 by telephone, with written confirmation transmitted on August 31, 1982. Both  
07 Containment spray systems were operable throughout the occurrence.

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
S B 11 B 12 B 13 P I P E X X 14 A 15 Z 16  
9 10 11 12 13 18 19 20

(17) LER/RO  
REPORT  
NUMBEREVENT YEAR  
8 2  
21 22SEQUENTIAL  
REPORT NO.  
0 8 9  
24 26OCCURRENCE  
CODE  
0 1  
28 29REPORT  
TYPE  
T  
30 31REVISION  
NO.  
0  
32ACTION TAKEN  
B 18 A 19  
33 34FUTURE ACTION  
Z 20  
35EFFECT ON PLANT  
Z 21  
36SHUTDOWN METHOD  
0 0 0 0  
37 40HOURS  
22ATTACHMENT  
SUBMITTED  
Y 23  
41NPRD-4  
FORM SUB.  
N 24  
42PRIME COMP.  
SUPPLIER  
A 25  
43COMPONENT  
MANUFACTURER  
W 1 2 0  
44 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The leak was due to failure of a Belzona repair made to the coil. The leaking coil  
11 was blanked off and No. 23 CFCU tested satisfactorily. At 1950 hours, August 30, 1982,  
12 No. 23 CFCU was declared operable and Action Statement 3.6.2.3b was terminated. Design  
13 Change Request 2EC-0505 will replace the coils with an erosion resistant material.

14 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
5 E 28 0 6 9 29 NA C 31 Containment Inspection  
8 9 10 11 12 13 44 45 46 80

15 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
6 Z 33 Z 34 NA NA  
8 9 10 11 12 13 44 45 80

16 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  
7 0 0 0 37 Z 38 NA  
8 9 10 11 12 13 44 45 80

17 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
8 0 0 0 40 NA  
8 9 10 11 12 13 44 45 80

18 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)  
9 Z 42 NA  
8 9 10 11 12 13 44 45 80

19 PUBLICITY ISSUED DESCRIPTION (45) 8209160281 820903  
0 N 44 NA S PDR ADOCK 05000311 PDR  
8 9 10 11 12 13 44 45 80

NRC USE ONLY

NAME OF PREPARER

R. Heiler

PHONE: (609) 541-5900 629