

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A R A N O 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 3 7 0 8 0 7 8 2 8 0 9 0 1 8 2 9
7 8 9 REPORT DATE 60 61 DOCKET NUMBER 66 67 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 On 8/7/82 during cooldown with reactor coolant system temperature at 307
0 3 F a control rod drive (CRD) D.C. breaker did not trip as required during
0 4 a surveillance. Redundant breakers were operable and would have allowed
0 5 the control rods to trip on a trip signal. This occurrence is reportable
0 6 per T.S.6.12.3.2.b. No similar occurrences have been reported relating
0 7 to CRD D.C. breakers, but similar occurrence relating to A.C. breakers
0 8 were reported in LER's 82-016, 78-029, 78-024 and 78-023.
7 8 9 80

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
R B 11 E 12 A 13 C K T B R K 14 A 15 Z 16
7 8 9 10 11 12 13 14 15 16 17

17 LER-RO REPORT NUMBER 18 12 19 20 21 22 23 24 25 26 27 28 29 30 31 32
EVENT YEAR 18 12 19 20 21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
B 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 Y 24 N 25 G 0 8 0 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 Inspection revealed that the undervoltage trip device was out of adjust-
1 1 ment. Proper adjustments were made, and the breaker was satisfactorily
1 2 bench tested. The breaker was returned to service and tested several
1 3 times to prove operability. The CRD breakers will be inspected on a
1 4 routine schedule to improve reliability.
7 8 9 80

1 5 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
D 28 0 0 0 0 29 RCS @ 307 F B 31 Routine Surveillance
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
Z 33 Z 34 NA NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
0 0 0 40 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
Z 42 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

2 0 PUBLICITY ISSUED DESCRIPTION (45)
N 44 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NRC USE ONLY

8209160371 820901
PDR ADOCK 05000313
S PDR

Patrick Rogers

PHONE 501/964-3100