



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 713 838-6631

September 1, 1982
RBG-13,308
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-60



On June 15, 1982, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning the installation of non-seismic pipe supports over Category I components in the Control Building at River Bend Station (DR-60). GSU has not completed its evaluation at this time. An interim or final status report will be provided by October 29, 1982.

Sincerely,

William J. Booker
for J. E. Booker

Manager-Engineering & Licensing
River Bend Nuclear Group

JEB/~~PK~~/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (RRI)

IE 27

8209160608 820901
PDR ADOCK 05000458
S PDR