

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

1	2	3	4	5	6
---	---	---	---	---	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

 M S G G S 1 

2	0	0	-	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

3	4	1	1	1	1
---	---	---	---	---	---

4	5
---	---

  
7 8 9 14 15 25 26 30 57 CAT 58  
LICENSEE CODE LICENSE NUMBER LICENSE TYPECON'T  

0	1
---	---

 REPORT SOURCE L 

6	0	5	0	0	0	4	1	6
---	---	---	---	---	---	---	---	---

7	0	8	3	0	8	2
---	---	---	---	---	---	---

8	0	9	2	2	8	2
---	---	---	---	---	---	---

9
---

  
7 8 60 61 68 69 74 75 80  
DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2
---	---

 | On August 30, the smoke detector zone covering the SSW pumphouse went into alarm and  

0	3
---	---

 | would not clear. The fire detection for the SSW pumphouse was therefore declared  

0	4
---	---

 | inoperable and a fire watch was established pursuant to T.S.3.3.7.9 until the zone  

0	5
---	---

 | was placed back into service. There was no effect on the health and safety of the  

0	6
---	---

 | public or threat to plant safety.  

0	7
---	---

 |  

0	8
---	---

 |

0	9
---	---

A	B
---	---

E
---

X
---

 I N S T R U 

E
---

Z
---

  
7 8 9 10 11 12 13 18 19 20  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  

17
----

 LER/RO REPORT NUMBER 

8	2
---	---

0	6	1
---	---	---

0	3
---	---

L
---

0
---

  
21 22 23 24 26 27 28 29 30 31 32  
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  

E
---

Z
---

Z
---

Z
---

0	0	0	0
---	---	---	---

N
---

N
---

X
---

H	2	6	0
---	---	---	---

  
33 34 35 36 37 40 41 42 43 44 47  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0
---	---

 | The zone alarm was caused by dust contamination of the ionization smoke detectors. All  

1	1
---	---

 | the detectors were cleaned and placed back into service. This is intended as a final  

1	2
---	---

 | report.  

1	3
---	---

 |  

1	4
---	---

 |

1	5
---	---

 G 

0	0	0
---	---	---

NA
----

A
---

 Alarmed Condition  
7 8 9 10 11 12 13 44 45 46  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  

1	6
---	---

 Z 

Z
---

NA
----

NA
----

NA
----

  
7 8 9 10 11 12 13 44 45 46  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  

1	7
---	---

0	0	0
---	---	---

NA
----

  
7 8 9 10 11 12 13 44 45 46  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  

1	8
---	---

0	0	0
---	---	---

NA
----

  
7 8 9 10 11 12 13 44 45 46  
PERSONNEL INJURIES NUMBER DESCRIPTION  

1	9
---	---

Z
---

NA
----

  
7 8 9 10 11 12 13 44 45 46  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  

2	0
---	---

N
---

NA
----

  
7 8 9 10 11 12 13 44 45 46  
PUBLICITY ISSUED DESCRIPTION  
8209300166 820922  
PDR AD0CK 05000416  
S PDR  
NRC USE ONLY  
7 8 9 10 11 12 13 44 45 46 68 69 80  
NAME OF PREPARER Original Signed by Ray Patterson PHONE: