



MAR 01 1982

Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

F.M.

August 24, 1981

LER # 263-81020

EVENT DATE 8/07/81

NSAC REC'D. 8/08/81

INPO REC'D. _____

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Leak in 1" Main Steam Drain

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.d since abnormal degradation of systems designed to contain radioactive material resulting from the fission process occurred.

Thomas M. Parker for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/TMP/bd

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA

Attn: J W Ferman

-over-

*IE22
BACKFIT
ADD:
M Collins 11*

8210150174 810824
PDR ADOCK 05000263
S PDR