



Duquesne Light

Nuclear Division
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 455-6000

September 30, 1982
ND1SS1:633

Beaver Valley Power Station, Unit No. 1
Docket No. 50-334, License No. DPR-66
LER 82-035/03L

Mr. R. C. Haynes, Regional Administrator
United States Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

In accordance with Appendix A, Beaver Valley Technical Specifications,
the following Licensee Event Report is submitted:

LER 82-035/03L, Technical Specification 3.2.1, Axial Flux Difference

Very truly yours,

W. S. Lacey
W. S. Lacey
Acting Superintendent

Attachment

8210150125 820930
PDR ADOCK 05000334
PDR

IE-2

Mr. R. C. Haynes
September 30, 1982
ND1551:633
Page 2

cc: Director Of Management & Program Analysis
United States Nuclear Regulatory Commission
Washington, D. C. 20555

J. Hultz, Ohio Edison

Director, Office of Inspection and Enforcement Headquarters
United States Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Peter Tam, BVPS Licensing Project Manager
United States Nuclear Regulatory Commission
Washington, D. C. 20555

W. M. Troskoski, Nuclear Regulatory Commission, BVPS Site Inspector

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator, Toledo Edison

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Arthur Alford, Stone & Webster/Boston