



October 19, 1982

Log No. K82-1512  
File: RR2 (NP-33-82-58)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Administrator, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

LER No. 82-049  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: September 20, 1982

Enclosed are three copies of Licensee Event Report which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosures

cc: Mr. Richard DeYoung, Director  
Office of Inspection and Enforcement  
Encl: 30 copies

Mr. Norman Haller, Director  
Office of Management and Program Analysis  
Encl: 3 copies

Mr. Tom Peebles  
NRC Resident Inspector  
Encl: 1 copy

8210280075 821019  
PDR ADOCK 05000346  
S PDR

THE TOLEDO EDISON COMPANY

EDISON PLAZA

300 MADISON AVENUE

TOLEDO, OHIO 43652

OCT 22 1982

IE22