



October 25, 1982

PNS-LJ-82-427

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-82-43

ST. LUCIE UNIT 1

DATE OF OCCURRENCE: SEPTEMBER 23, 1982

TECHNICAL SPECIFICATION 3.3.3.8

LOSS OF SUBCOOLED MARGIN MONITOR

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. Williams, Jr.", is written over the typed name.

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWw/PKG/mpc

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1

82 OCT 29 AID: 34
USNRC REGION II
ATLANTA, GEORGIA

OFFICIAL COPY

IE 22

8211040086 821025
PDR ADOCK 05000335
S PDR