

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

REPORT
SOURCE

60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80				
	6	0	5	0	0	0	3	6	6	7	0	9	2	4	8	2	8	1	0	2	1	8	2	9
		DOCKET NUMBER							EVENT DATE							REPORT DATE								

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On September 24, 1982, with Unit 2 in run at 2398 MWt, the "2D" RHR pump
03 would not start with the control switch when required. Tech. Specs.
04 3.5.3.2 requires four operable RHR pumps. The remaining RHR pumps and
05 the core spray system were operable. The unit was put in a 7-day Limiting
06 Condition for Operation (LCO) per Tech. Specs. 3.5.3.2, action a.1. The
07 health and safety of the public were not affected by this non-repetitive
08 event.

0 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
		C	F	E		A		C	K	T	B	R	K	A	
(17) LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
21		22		23		24		25		26		27		28	
8		2		1		0		4		0		3		L	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
33		34		35		36		37		38		39		40	
A		Z		Z		Z		0		N		N		A	
(18)		(19)		(20)		(21)		(22)		(23)		(24)		(25)	
COMPONENT MANUFACTURER															
44		45		46		47		48		49		50		51	
S		3		4		5		6		7		8		9	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of the event was component failure of the pump breaker due to

1 1 a broken relay snap ring. The relay snap ring was replaced, and the

1 2 breaker was successfully tested and pump operation verified by using the

1 3 control switch. The pump was returned to service on September 24, 1982.

1 4

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	E	28	0	9	8	29	NA	30	A	31	Operator Observation							
ACTIVITY CONTENT				RELEASED OF RELEASE				AMOUNT OF ACTIVITY				LOCATION OF RELEASE							
1	6	Z	33	Z	34	NA	35	NA	36										
PERSONNEL EXPOSURES				PERSONNEL INJURIES				PERSONNEL EXPOSURES				PERSONNEL INJURIES							
NUMBER				TYPE				DESCRIPTION				NUMBER				DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	39	0	0	0	40	NA	41				
LOSS OF OR DAMAGE TO FACILITY				PUBLICITY				ISSUED				NRC USE ONLY							
TYPE				DESCRIPTION				DESCRIPTION											
1	9	Z	42	NA	43	NA	44	NA	45										
2	0	N	44	NA	45														

NAME OF PREPARER S. B. Tipps

PHONE: (912) 367-7851