



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

October 28, 1982

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1

Docket No. 50-416

License No. NPF-13

File Q260/L-835.0

Fuel Handling Area Vent Supply

Isolation Damper Failed to

Close in Less Than 5

Seconds During Routine

Surveillance

Reference: LER 82-093/03 L-0

AECM-82/511

With the Plant in Hot Shutdown, during Non-Nuclear Heatup, the Fuel Handling Area Vent Supply Isolation Damper (Q1T42F0012) failed to cycle closed in less than 5 seconds. This report is being submitted per T.S.3.6.6.2 and 6.9.1.13.b. Attached is LER 82-093/03 L-0.

Yours truly,

J. P. McGaughy, Jr.
For J. P. McGaughy, Jr.

JPM:sap
Attachment

cc: Mr. N. L. Stampley (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8211040264 821028
PDR ADOCK 05000416
S PDR

Member Middle South Utilities System

OFFICIAL COPY

IE 22