



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
POST OFFICE BOX 790
HARTSVILLE, SOUTH CAROLINA 29550

SNRC REGION
ATLANTA, GEORGIA

NOV 8 3:00

NOV 03 1982

Robinson File No: 135100

Serial: RSEP/82-1822

Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
LICENSEE EVENT UPDATE REPORT 82-005, REVISION 1

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit No. 2, the enclosed Licensee Event Report is submitted. The original report, dated July 12, 1982, described the condition of "B" Main Steam Check Valve which could have rendered it inoperable. The enclosed update report completely describes the original event and clarifies the method of discovery and corrective actions which have been taken. Additionally, this update report contains information from the valve vendor relating to unmodified check valves as requested in IE Report 82-23. This report, therefore, supersedes and should replace all copies of the original report.

Very truly yours,

R. B. Starkey, Jr.
General Manager
H. B. Robinson SEG Plant

HTC/bss

Enclosure

cc: R. C. DeYoung (40)
R. A. Hartfield (3)

8211100379 821103
PDR ADOCK 05000261
S PDR

OFFICIAL COPY
IE22