




**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

November 9, 1982

DJS Ltr. #82-1136

James G. Keppler, Regional Administrator  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reportable Occurrence Report #82-42/01T-0, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(c), abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment.

  
for D. J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Management Branch  
File/NRC

NOV 10 1982

8211160423 821109  
PDR ADOCK 05000249  
S PDR

IE 22