

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

November 11, 1982

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-74 was to have been submitted by November 12, 1982. This 30 day reportable occurrence (pursuant to T.S.6.9.1.13) concerns T.S.3.6.1.3, "Each containment air lock shall be operable...", which was violated on October 14, 1982. However, the investigation of this incident and preparation of a report are incomplete at this time. The report will now be submitted by November 30, 1982.

Very truly yours,

H.B. Tucker

Hal B. Tucker

PBN/jfw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector
McGuire Nuclear Station

8211220199 821111
PDR ADOCK 05000369
S PDR

OFFICIAL COPY
IE 22

NOV 16 AID: 23
USNRC REGION II
ATLANTA, GEORGIA