

50.55(e) Report

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

November 8, 1982  
ANPP-22217-GHD/BSK

U. S. Nuclear Regulatory Commission  
Region V  
Creskside Oaks Office Park  
1450 Maria Lane - Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. D. V. Sternberg, Chief  
Reactor Projects Branch 1

Subject: Deficiency Evaluation Report 82-52  
A 50.55(e) Evaluation Relating to Nonconformances on  
Previously Inspected Pipe Supports In Unit 1 Auxiliary  
Building  
File: 82-019-026  
D.4.33.2


Reference: Telephone Conversation between T. Young and G. Duckworth  
on October 7, 1982

Dear Sir:

The NRC was notified of the subject Deficiency Evaluation in the referenced telephone conversation, with a determination of reportability to be made within thirty (30) days (November 8, 1982).

The deficiency has subsequently been determined to be Not Reportable under the requirements of 10CFR50.55(e), therefore, no written report is required. Necessary documentation of the evaluation will be maintained in APS files.

Very truly yours,



E. E. Van Brunt, Jr.  
APS Vice President  
Nuclear Projects Management  
ANPP Project Director

EEVBJr/GHD:db

cc: See Attached Page 2

U. S. Nuclear Regulatory Commission  
Attention: Mr. D. M. Sternberg, Chief  
Page 2

November 8, 1982  
ANPP-22217-GHD/BSK

cc: Richard DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

T. G. Woods, Jr.  
J. A. Roedel  
D. B. Fasnacht  
G. C. Andognini  
A. C. Rogers  
B. S. Kaplan  
W. E. Ide  
J. Vorees  
J. A. Brand  
A. C. Gehr  
W. J. Stubblefield  
W. G. Bingham  
R. L. Patterson  
R. W. Welcher  
R. M. Grant  
D. R. Hawkinson  
L. E. Vorderbrueggen  
G. A. Fiorelli

Lynne Bernabei, Esq.  
Harmon & Weiss  
1725 "I" Street, NW  
Suite 506  
Washington, D. C. 20006

R. L. Greenfield  
Assistant Attorney General  
Bataan Memorial Building  
Santa Fe, New Mexico 87503