

U-0325  
L14-81(11-04)-L

November 4, 1981

Mr. James G. Keppler  
Director, Region III  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Deficiency 81-04  
10CFR50.55(e)  
Inconsistencies in the Certifications  
for HVAC Materials (Zack)

On October 2, 1981, Illinois Power verbally notified Mr. H. M. Wescott, NRC Region III, of a potential reportable deficiency per 10CFR50.55(e) concerning inconsistencies in the certification for Clinton Project HVAC materials (Zack).

Our investigation of this matter has not been completed, and this is to serve as an interim report per 10CFR50.55(e)(3). A detailed analysis of the safety implications cannot be accomplished until the missing or corrected certifications have been obtained and any nonconforming conditions identified for engineering evaluations. We anticipate that we will need approximately 60 days to complete our investigation of this potential deficiency and the determination of reportability.

Sincerely,

*L.J. Koch* FOR  
L.J. Koch  
Vice President

GWB/rlj

cc: H.H. Livermore, NRC Resident Inspector  
Director, Office of I&E, USNRC, Washington, DC 20013  
Director-Quality Assurance

8111130443 811104  
PDR ADOCK 05000461  
S PDR

IE27  
S  
1/0

IE27

NOV 9 1981