

TENNESSEE VALLEY AUTHORITY
USNRC REGION II
CHATTANOOGA, TENNESSEE 37401
ATLANTA, GEORGIA

1750 Chestnut Street Tower II

81 NOV 9 A 8:44

November 6, 1981

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/8162

The enclosed report provides details concerning diesel generator 3C
which was made inoperable to calibrate relay PFD1. This report is submitted
in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Loney
J. A. Loney
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555


Director (40)

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center

Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry



8111130638 811106
PDR ADOCK 05000296
S PDR

Equal Opportunity Employer

OFFICIAL COPY

IE 22
3
11