



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

October 5, 1981

1CAN108102

Mr. G. L. Madsen, Chief
Reactor Projects Branch
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76102



SUBJECT: Arkansas Nuclear One - Unit 1
Docket No. 50-313
License No. DPR-51
Licensee Event Report No. 81-013/03L-0
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2.b, attached is the subject report concerning a leak discovered in the weld of a drain line of the "A" Decay Heat Pump discharge piping. This LER is being submitted late due to an administrative oversight which caused a delay in processing.

Very truly yours,

David C. Trimble
for David C. Trimble
Manager, Licensing

DCT:GAC:rlg

cc: Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8111170222 811005
PDR ADOCK 05000313
S PDR

MEMBER MIDDLE SOUTH UTILITIES SYSTEM

1E22
3
11