



Carolina Power & Light Company


September 17, 1981

File: NG-3513(R)

Serial No.: NO-81-1526

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 3170  
101 Marietta Street, N.W.  
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
RESPONSE TO IE BULLETIN 81-02, SUPPLEMENT NO 1



Dear Mr. O'Reilly:

In response to your letter of August 18, 1981, transmitting a supplement to IE Bulletin 81-02, Carolina Power & Light Company submits the following response for H. B. Robinson Steam Electric Plant.

A thorough review has determined that there are no gate type valves of this manufacture in use, or maintained as spares, at the H. B. Robinson Plant.

The manpower expended for this review and for the required report preparation was approximately 20 man hours.

We trust that this satisfies the requirements of IE Bulletin 81-02, Supplement No. 1.

Yours very truly,

B. J. Furr  
Vice President  
Nuclear Operations

SHC/lr (7803)

cc: Victor Stello, Jr.

B. J. Furr, having been first duly sworn, did depose and say that the information contained herein is true and correct to his own personal knowledge or based upon information and belief.

Notary Public

My commission expires: My Commission Expires 6-8-86

8111170258 810917  
PDR ADOCK 05000261  
g PDR  
iteville Street • P. O. Box 1551 • Raleigh, N. C. 27602

IE 11  
5/10