

ILLINOIS POWER COMPANY



0981-L
U-0308
Q37-81(10-13)-L
500 SOUTH 27TH STREET, DECATUR, ILLINOIS 62525
October 13, 1981

Mr. R.L. Spessard, Director
Division of Resident and Project Inspection
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 61037

Dear Mr. Spessard:

This is in response to your Notice of Violation and Inspection Report 50-461/81-22. Illinois Power Company's response to the item of noncompliance cited is as follows:

1. The Notice of Violation states, in part:

"Contrary to the above, the Contractor was performing stainless steel welding operations using oversize electrode (5/32") and unmarked wire brushes, discs, chisel, and chipping hammers."

A. Corrective action taken and the results achieved:

Use of the oversized electrode was stopped immediately when the procedural violation was brought to supervisory attention. Unmarked tools were replaced with tools marked for use on stainless steel. A nonconformance report (NCR) 5263 was written and processed to document the use of the oversize welding electrode.

B. Corrective Action taken to avoid further noncompliance:

Affected craft and technical services personnel were given training emphasizing adherence to written procedures and control of stainless steel materials. Additionally, the pertinent welding procedure specification (NP-8-8-BA-L) has been revised to allow the use of 5/32" welding electrode.

C. Date when full compliance will be achieved:

The Contractor is now in full compliance with regulatory and procedural requirements.

OCT 16 1981

October 13, 1981

I trust that our response is satisfactory to allow closure of this item of noncompliance noted in the Notice of Violation and Inspection Report Number 50-461/81-18. I hereby affirm that the information contained in this letter is correct to the best of my knowledge.

Sincerely,

AJBudmil FOR

L.J. Koch
Vice President

AJB/rlj

cc: H.H. Livermore, Resident NRC Inspector
Director-Quality Assurance