



November 10, 1981

Log No. K81-96

File: RR 2 (NP-33-81-74)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 81-065
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: October 11, 1981

Enclosed are three copies of Licensee Event Report 81-065 with a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray /smq

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station


TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy



NOV 13 1981

8111170313 811110
PDR ADDOCK 05000346
PDR

EDISON PLAZA

300 MADISON AVENUE

TOLEDO, OHIO 43652

IE 22