



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

November 13, 1981

Director, I&E Region III  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137



PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-282 License No. DPR-42

Breaker for Heat Trace Rack No. 1 Found Tripped

The Licensee Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.(b), since it represents operation in a degraded mode permitted by a limiting condition for operation.

L O Mayer, PE  
Manager of Nuclear Support Services

LOM/DMM/bd

cc: NRC Document Control Desk (1)  
NRC Resident Inspector  
MPCA  
Attn: J W Ferman

8111190510 811113  
PDR ADOCK 05000282  
S PDR

NOV 16 1981

IE 22 S11