

November 9, 1981



Log No. K81-92

File: RR 2 (NP-33-81-75)

Docket No. 50-346

License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence 81-064
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: October 12, 1981

Enclosed are three copies of Licensee Event Report 81-064 with a supplemental information sheet which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray /smq

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy

8111190533 811109
PDR ADOCK 05000346
S PDR

COMPANY

EDISON PLAZA

300 MADISON AVENUE

TOLEDO, OHIO 43652

NOV 16 1981

IE22
S11