

CONTROL BLOCK: 

--	--	--	--	--	--	--

1

0	1	W	I	P	B	H	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE							14	LICENSE NUMBER										25	LICENSE TYPE					30	57 CAT		58

7 8

REPORT SOURCE

30 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

0 1 L 6 0 5 0 0 0 2 6 6 7 1 0 1 6 8 1 8 1 1 1 3 8 1 9

02 While temporarily connecting wet pipe flow switches into the EDG area  
03 smoke detection system, a wiring error caused system supply fuses to  
04 blow. Operators acknowledged the alarm, assumed that the fault was  
05 confined to the EDG area, and inspected that area as required by Tech-  
06 nical Specification 15.3.14.D. In a discussion following the 2.5 hour  
07 repair, operators learned that the entire smoke detection system had  
08 been inoperable during the repair.

09		SYSTEM CODE A B		CAUSE CODE A	CAUSE SUBCODE A	COMPONENT CODE Z Z Z Z Z Z					COMP. SUBCODE Z	VALVE SUBCODE Z
7	8	9	10	11	12	13	14	15	16			
LER/RO REPORT NUMBER		EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 1 8		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		
17	18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN Z		FUTURE ACTION H		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N
33	34	35	36	37	38	39	40	41	42	43	44	45
PRIME COMP. SUPPLIER Z		COMPONENT MANUFACTURER 9 9 9										
46	47	48	49	50	51	52	53	54	55	56	57	58

1 0 The alarm was reportedly caused by blown fuses. Since electricians were  
1 1 working on the system at the time, operators were satisfied with this  
1 2 explanation and did not follow up to determine which areas were affected.  
1 3 Emphasis on the importance of following up all alarms, even only to  
1 4 verify a seemingly obvious apparent cause will be conveyed to personnel.

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1	5	H (28)	0	0	0 (29)	N/A			A (31)	System Alarm (32)			

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z (33) 2 (34) N/A

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

44

LOCATION OF RELEASE (36)

N/A

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	N/A	(39)

PERSONNEL INJURIES		DESCRIPTION (41)	
NUMBER			
1	8	0	0
0	0	0	40
		N/A	

8 9		11 12		80	
LOSS OF OR DAMAGE TO FACILITY (43)					
TYPE		DESCRIPTION			
1 9	Z (42)	N/A			

7 8 9 10 8111200810 811113  
 PUBLICITY PDR ADOCK 05000266 NRC USE ONLY  
 ISSUED DESCRIPTION (45) S PDR  
 (2) (0) (N) (44) N/A

NAME OF PREPARER C. W. Fay

PHONE: 414/277-2811

SPQ 917-926