


TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
REGION II
1750 Chestnut Street Tower II GEORGIA

01 NOV 30 AIO : 44

November 24, 1981



Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRC-50-259/81064

The enclosed report provides details concerning switch No. 1 of PS-3-74A
and switch No. 2 of PS-3-47B which were outside technical specification
limits by 1.57 psi and 13.43 psi respectively. This report is submitted
in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.b(1).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
J. J. Green

Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

OFFICIAL COPY

IE 22
S11

8112070193 811124
PDR ADOCK 05000259
S PDR

An Equal Opportunity Employer