

# CP&L

Carolina Power & Light Company

P.O. Box 10429  
Southport, NC 28461  
March 10, 1993

ROY A. ANDERSON  
Vice President  
Brunswick Nuclear Plant

File: B09-13510  
Serial: BSEP 93-0027

Mr. Stewart D. Ebnetter  
Regional Administrator  
United States Nuclear Regulatory Commission  
101 Marietta Street, N. W., Suite 2900  
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 AND 2  
DOCKET NO. 50-325 AND 50-324/ LICENSE NO. DPR-71 AND DPR-62  
CONFIRMATORY ACTION LETTER  
REVISION TO METHODOLOGY USED TO MANAGE THE PERFORMANCE  
IMPROVEMENT PROGRAM SHORT TERM ACTIONS

Dear Mr. Ebnetter:

The purpose of this letter is to notify the NRC of a change to a commitment referenced in the Confirmatory Action Letter dated December 18, 1992, for Enclosure 3 of Carolina Power & Light Company's (CP&L) letter dated July 23, 1992. As stated in the Confirmatory Action Letter, CP&L will "...agree to complete the specific issues identified for Unit 2 in Enclosure 3 of your July 23, 1992 letter prior to restart of the unit...."

Enclosure 3 of CP&L's July 23, 1992 letter provided a list of actions that will be completed prior to startup. The list included work items that were the subject of previous docketed commitments which were identified and will be managed by using the methodology listed in Enclosure 2.

Enclosure 2 of CP&L's July 23, 1992 letter provided the methodology for establishing corrective actions as pre- or post-startup. The "Enclosure 2 methodology" was proceduralized in Brunswick Nuclear Plant Procedure PN-30, "Integrated Recovery Methodology," which has been effective since October 2, 1992.

PN-30 has recently been revised (Revision 2, informational copy attached) to clarify the role of the Plant Nuclear Safety Committee (PNSC) in the rescheduling of maintenance not performed in the outage. This revision is intended to ensure more effective utilization of the PNSC in the PN-30 process by focusing its attention on higher priority issues. The Unit 2 Plant Manager, will continue to review all items proposed to be rescheduled.

170050

9303170171 930310  
PDR ADDCK 05000324  
P PDR


IE36  
11

Mr. S. D. Ebner  
BSEP 93-0027 / Page 2

Since the current Revision 2 to PN-30 provides a different methodology for establishing corrective actions as pre- or post-startup from that referenced in Enclosure 3 of CP&L's July 23, 1992 letter, we are informing the NRC of this change.

If you have questions please contact me at (919) 457-2495.

Yours very truly,

  
R. A. Anderson

SHC/shc (BSEP9327.001)

Enclosure

cc: NRC Document Control Desk  
Mr. P. D. Milano  
Mr. R. L. Prevatte

bcc: Mr. R. A. Anderson  
T. A. Baxter, Esq.  
Mr. E. A. Bishop  
Mr. M. D. Bradley (BNP)  
Mr. J. M. Brown (BNP)  
Mr. R. K. Buckles (LIS)  
Mr. S. H. Callis (BNP)  
Mr. M. S. Calvert (BNP)  
Mr. J. Cowan (BNP)  
Mr. R. C. Godley (BNP)  
Mr. J. L. Harness  
Mr. E. M. Harris  
Mr. J. D. Heidt  
Mr. W. G. Hindman

Mr. M. A. Jones (BNP)  
Mr. A. M. Lucas  
Mr. R. E. Morgan (BNP)  
Mr. E. M. Northeim  
Mr. H. A. Pollock  
Mr. W. W. Simpson  
Mr. R. B. Starkey, Jr.  
Mr. G. H. Warriner (BNP)  
Mr. D. B. Waters  
Mr. R. A. Watson  
Mr. E. E. Willett (BNP)  
File: BC/A-4  
File: B-X-0274

ENCLOSURE

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 AND 2  
NRC DOCKET NOS. 50-325 AND 50-324  
OPERATING LICENSE NO. DPR-71 AND DPR-62  
BRUNSWICK NUCLEAR PLANT PROCEDURE PN-30, REVISION 2