



South Carolina Electric & Gas Company  
P.O. Box 88  
Jenkinsville, SC 29065  
(803) 345-4040

John L. Skolds  
Vice President  
Nuclear Operations

March 25, 1993  
Refer to: RC-93-0079

Mr. S. D. Ebnetter  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II, Suite 2900  
101 Marietta Street, NW  
Atlanta, GA 30323

Dear Mr. Ebnetter:

Subject: VIRGIL C. SUMMER NUCLEAR STATION  
DOCKET NO. 50/395  
OPERATING LICENSE NO. NPF-12  
SPECIAL REPORT (SPR 930002) (ONO 930019)

This Special Report is being submitted pursuant to the requirements of Station Administrative Procedure (SAP) 131A, "Fire Service Equipment/Systems Operability Requirements."

At 1650 hours on March 10, 1993, the Diesel Driven Fire Service Pump (XPP-134B) was removed from service. With the plant in Mode 5 and in day 6 of a sixty-five day refueling outage, the fire pump was removed from service to facilitate the inspection and removal of Asiatic Clams from the pump's water supply bay area.

Due to unforeseen delays, inspection of the bay area by divers was not completed in the outage time (seven days) allowed by procedure. The fire pump was returned to service at 0640 hours on March 20, 1993.

Should you have any questions, call at your convenience.

Very truly yours,

John L. Skolds

RJB:lcd

c: O. W. Dixon  
R. R. Mahan  
R. J. White  
G. F. Wunder  
S. R. Hunt  
NRC Resident Inspector

Marsh & McLennan  
Document Control Desk  
INPO Records Center  
NSRC  
RTS (ONO 930019)  
File (818.05 & 818.08)

9304050057 930325  
PDR ADOCK 05000395  
S PDR

NUCLEAR EXCELLENCE - A SUMMER TRADITION!

JE22 1/0