



▼ 9760 SHEPARD ROAD ▼

MACEDONIA, OHIO 44058

Phone: (216) 467-0200

March 31, 1993

Document Control Desk  
Office of Nuclear Reactor Regulation  
Nuclear Regulatory Commission  
Washington, D.C. 20555

Subject: Defects Potentially Reportable Under 10CFR21

Dear Sir:

We are writing to inform you about a possible material defect in a stainless steel Cajon pipe fitting, part number SS-4-CP.

This fitting may contain an inclusion within the raw material from which it was produced. This inclusion could cause the fitting to leak.

A list of the nuclear facilities to which this part has been sold is enclosed.

The number of fittings which have this defect is believed to be less than .6% of all fittings produced from this material.

The supplier of this material, Crucible Specialty Metals, has been notified. Establishment of cause and subsequent corrective action has been initiated by Crucible.

If you have any questions, please do not hesitate to contact us.

Sincerely,

*David J. Johnston*  
David J. Johnston  
General Manager

Enclosure

DJJ/cm

PDR

290063

9304300062 930331  
PDR ADOCK 05000346  
S PDR

PRECISION PIPE FITTINGS ▼ WELD FITTINGS ▼ VACUUM COUPLINGS

JE19 1/0



A SWAGELOK® COMPANY

▼ 9760 SHEPARD ROAD ▼

MACEDONIA, OHIO 44056

Phone: (216) 467-0200

Niagara Mohawk Power Corp.  
Nine Mile Unit II  
Lake Road  
Scriba, NY 13093  
Order #93342

50 pcs.

Toledo Edison Company  
Davis-Besse  
5501 N. State Route 2  
Oak Harbor, OH 43449-9760  
Order #B041976 D92 Rel. #4  
Order #B041976 D92 Rel. #009

40 pcs.  
20 pcs.