



Florida Power

CORPORATION
Crystal River Unit 3
Docket No. 50-302

May 3, 1993
3F0593-05

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Subject: Containment Emergency Sump Spray pH Control System

Reference: NRC to FPC letter, 3N0792-14, dated July 23, 1993

Dear Sir:

The reference letter requested that Florida Power Corporation (FPC) advise the NRC when the Containment Emergency Sump pH Control System was placed in service. The Cycle 9 mid-cycle outage was completed on April 26, 1993. The new pH control system using trisodium phosphate dodecahydrate (TSP-C) was operable prior to entering Mode 4 as required by Technical Specification 3.6.2.2.

Sincerely,

P. M. Beard, Jr.
Senior Vice President
Nuclear Operations

PMB/JWT:ff

xc: Regional Administrator, Region II
Senior Resident Inspector
NRR Project Manager

100064

9305110266 930503
PDR ADDCK 05000302
P PDR

A Florida Progress Company

AC01 1/0