

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736 8001



John H. Garrity
Resident Manager

May 6, 1993
IPN-93-031

Docket No. 50-286
License No. DPR-64

Mr. Thomas T. Martin, Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Dear Mr. Martin:

In accordance with 10CFR50.4(b)(5), one (1) copy of the most recent revisions to our Emergency Plan/Procedures has been sent to the NRC Document Control Desk in Washington, D.C. Two (2) copies have been sent to your office, Emergency Preparedness Section, and one (1) copy has been sent to the IP-3 Resident Inspector.

These changes have been evaluated against 10CFR50.54(q) and have been determined not to decrease the effectiveness of the Indian Point 3 Emergency Plan. The Plan and Procedures, as changed, continue to meet the standards of 10CFR50.47 and Appendix E.

Sincerely,

A handwritten signature in cursive script that reads "John H. Garrity".

John H. Garrity
Resident Manager
Indian Point No. 3 Nuclear Power Plant

JHG/DB/lat

cc: Document Control Desk (original)
U.S. Nuclear Regulatory Commission
Washington, D.C. 20535

Resident Inspector's Office
U.S. Nuclear Regulatory Commission
Indian Point No. 3
P.O. Box 337
Buchanan, New York 10511

9305140188 930504
PDR ADOCK 05000286
F PDR

35
1/0