

To whom it may concern,

In my opinion the McGuire Nuclear Station, which is located less than twenty miles north of my home, is not safe.

The study of June 26, 1980, SECY 80-107 "proposed interim Hydrogen Control Requirements for Small Containment" has convinced me that the McGuire station is incapable of holding hydrogen pressure equal to the pressure experienced at the Three Mile Island station. I urge you to reopen the McGuire licensing hearings for the safety of our community.

very sincerely,

Margaret Anne Underwood



DOCKET NUMBER
PROD. & UTIL. FAC. 50-369/370

8101090514

H

503
5
10