

CONTRQL BLOCK:

--	--	--	--	--	--

 ①

0	1	N	J	O	C	P	1	2	0	0	-	0	0	0	0	0	-	0	3	4	1	1	1	1	4			5				
1	2	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57 CAT 58				

REPORT SOURCE L 6 0 5 0 0 0 2 1 9 7 0 7 2 2 8 1 8 0 0 2 1 0 1 9

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

0 2 During a load reduction after failure of traveling screens 1 & 2 and the
0 3 removal of circulating pump 1-1 from service, the control rod configura-
0 4 tion resulted in a peaking factor that was 110% of its allowable limit.
0 5 When this result became available from the plant process computer,
C 6 actions were already underway to return the control rod pattern to its
0 7 steady state configuration.

08 | _____

09		SYSTEM CODE Z Z		11	CAUSE CODE A		12	CAUSE SUBCODE B		13	COMPONENT CODE Z Z Z Z Z Z					14	COMP. SUBCODE Z		15	VALVE SUBCODE Z		20	
17		LER NO REPORT NUMBER		EVENT YEAR 8 1		21	22	SEQUENTIAL REPORT NO. 0 3 4		24	26	OCCURRENCE CODE 0 3		28	29	REPORT TYPE L		30	REVISION NO. 0		32		
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		22	ATTACHMENT SUBMITTED		23	NPRD-4 FORM SUB.		24	PRIME COMP. SUPPLIER		25	COMPONENT MANUFACTURER		26	
G		18	Z		19	Z		20	0 0 0 0		22	Y		23	N		24	Z		25	Z 9 9 9		26
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	

1 0 The apparent causes of this occurrence are attributed to personnel error

1 1 and procedural inadequacy in the review of control rod configuration

1 2 instructions for off-hours load maneuvers. The revision to procedure

1 3 1001.22 initiated as a result of this occurrence should effectively

1 4 ensure that this situation will not recur.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
1	5	F	28	0	29	N/A	30	A	31	Computer Output	32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 34

AMOUNT OF ACTIVITY (35)
N/A

LOCATION OF RELEASE (36)
N/A

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		(37)	Z	(38) N/A

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	(40) N/A

		8		9		10		11		12			
LOSS OF OR DAMAGE TO FACILITY						(43)							
TYPE						DESCRIPTION							
1	9	Z	(42)	N/A									

8 9 10
PUBLICITY
ISSUED DESC
3 0 N 44
8 9 10
8108310110 810821
PDR ADOCK 05000219
S PDR
NRC USE ONLY
68 69 70 71 72 73 74 75 76 77 78 79 80
80

NAME OF PREPARER

PHONE