

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N.C. 28202

USNRC REGION II
ATLANTA, GEORGIA

82 MAY 2 All: 41

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

April 23, 1982

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:JPO
Catawba Nuclear Station
Docket Nos. 50-413 and 50-414

Dear Mr. O'Reilly:

In response to your August 18, 1981 letter which transmitted IE Bulletin 81-02, Supplement 1, pursuant to 10 CFR 50.55(e), Significant Deficiency Report SD 413-414/82-09 dated April 9, 1982 was sent in response to the concerns brought forth by this Bulletin. As indicated under the Corrective Action, a final report will be sent by June 17, 1982.

Very truly yours,



William O. Parker, Jr.

RWO/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. P. K. Van Doorn
NRC Resident Inspector
Catawba Nuclear Station

Mr. Robert Guild, Esq.
Attorney-at-Law
314 Pall Mall
Columbia, South Carolina 29201

Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

OFFICIAL COPY

8205180113

IE 27
3
111