




ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

April 22, 1982

2CANØ48211

Mr. W. C. Seidle, Chief  
Reactor Project Branch #2  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



SUBJECT: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report  
No. 82-007/03X-1  
(File: 2-0520)



Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specifications 6.9.1.9.b and 6.9.1.9.d, attached are the subject reports concerning two leaks which were discovered, one in a weld for a drain line and the other in a weld on a suction accumulator. Both leaks are associated with charging pump, 2P-36C. This is an update to a previous submittal dated March 5, 1982.

Very truly yours,

John R. Marshall  
Manager, Licensing

JRM:GAC:sc

Attachment

cc: Mr. Richard C. DeYoung  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Norman M. Haller, Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

8205040362 820422  
PDR ADDCK 05000368  
S PDR