

CONTROL BLOCK: 

--	--	--	--	--	--	--

7

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER											25	26	LICENSE TYPE				30	57	CAT	58

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	7	2	7	0	4	0	5	8	2	8	0	4	2	1	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On April 5, 1982, during monthly surveillance, the Control Room Operator observed

03 | that the service water flow to No. 14 Containment Fan Coil Unit (CFCU) was less

04 | than the 700 GPM required. No. 14 was declared inoperable at 1231 hours, and

0	5	Action Statement 3.6.2.3.a was declared.
---	---	--

0	6
---	---

0	7	
---	---	--

0	8	
---	---	--

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
0	9	S	B	E		X		V	A	L	V	E	A		G
7	8	9	10	11	12	13		14	15	16	17	18	19	20	
(17) LER RO REPORT NUMBER		EVENT YEAR				SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
21		8 2		22		0 2 2		0 3		L		0			
23		24		25		26		27		28		29			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.			
E		Z		Z		Z		0 0 0 0		Y		N			
18		19		20		21		22		23		24			
33		34		35		36		37		40		42			
PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER													
L		F 1 3 0													
25		26													
43		44		45		46		47		48		49			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The reduced service water flow to No. 14 CFCU resulted from a decrease in the out-
---	---	--

11 Input of Flow Control Valve 14SW57 high speed air supply regulator. The high speed

[1] [2] | regulator was blown down, the setpoint was readjusted, and No. 14 CFCU was satis-

13 | factorily tested. The unit was declared operable at 1722 hours, April 5, 1982 and

1	4	Action Statement 3.6.2.3.a was terminated.
---	---	--

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	G	28	0	0	0	29	N/A	B	31	Surveillance Test			
7	8	9	10	11	12	13	44	45	46	80				
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	6	Z	33	Z	34	N/A			N/A					
7	8	9	10	11	12	13	44	45	46	80				
PERSONNEL EXPOSURES			NUMBER			TYPE			DESCRIPTION					
1	7	0	0	0	37	Z	38	N/A						
7	8	9	10	11	12	13	44	45	46	80				
PERSONNEL INJURIES			NUMBER			DESCRIPTION								
1	8	0	0	0	40	N/A								
7	8	9	10	11	12	13	44	45	46	80				
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION								
1	9	Z	42	N/A										
7	8	9	10	11	12	13	44	45	46	80				
PUBLICITY			ISSUED			DESCRIPTION			NRC USE ONLY					
2	0	N	44	N/A										
7	8	9	10	11	12	13	44	45	46	80				

NRC USE ONLY