



**LOUISIANA**  
**POWER & LIGHT**


142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 30, 1982

G. D. McLENDON  
Senior Vice President

W3K-82-0256  
Q-3-A35.07.47

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 47  
Second Interim Report  
"General Electric AKR-30/50 Circuit Breakers Closing Spring Screw"

Reference: 1) LP&L letter W3K-82-0146 to NRC dated March 15, 1982  
2) Telecon - L. L. Bass (LP&L) to B. Crossman (NRC) on 4/27/82

Dear Mr. Collins:

In reference 1, LP&L committed to submitting a final report on SCD No. 47 by April 30, 1982. Since that time, we have experienced problems in obtaining the correct replacement part from General Electric. At this time, we are awaiting receipt of replacement material.

Based on the above information, a final report will be submitted by May 31, 1982.

Very truly yours,

*G. D. McLendon*

GDMcL/LLB/grf

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555



8205070226 820430  
PDR ADOCK 05000382  
S PDR

*IE 27*  
*S/0*