

71

DN'T

60 L 61 0 5 0 0 0 3 3 6 7 0 4 1 9 8 2 8 0 5 0 3 8 2 9
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During a routine startup, review of Technical Specifications Section 3.5.2.d Emergency Core Cooling System (ECCS) Subsystems revealed mode changes had occurred while operating under action statement "a" because an inoperable valve disabled a required boric acid flow path. The valve was returned to operable status and operation continued in accordance with the Technical Specifications. The total time in the action statement was 47 hours.

SYSTEM
CODE
S | F

CAUSE
CODE
A

CAUSE
SUBCODE
A
12

COMPONENT CODE

COMP.
SUBCODE
[Z]
19

VALVE
SUBCODE
Z ()
20

REVISION
NO.
[0]

17 LER RO
REPORT
NUMBER

EVENT YEAR
8 2
21 22

SEQUENTIAL
REPORT NO.
0 | 0 | 9

OCURRENCE
CODE
0 1
28 29

REPORT
TYPE
[T]
30

COMPONENT
MANUFACTURER
17 19 19 10

| ACTION TAKEN | FUTURE ACTION |
|-----------------|------------------|
| H | X |
| 33 | 34 |

EFFECT
ON PLANT

[Z] (2)

35

SHUTDOWN
METHOD
Z (2)
36

HOURS
0 | 0

ATTACHMENT
SUBMITTED
[Y] (23)
41

NPRD-4
FORM SUB
[Y] (C)
42

PRIME COMP
SUPPLIER
LZ (2)
43

COMPONENT
MANUFACTURER
| Z | 9 | 9 | 9 | (26)
44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The mode changes made while operating in the action statement occurred because of a misinterpretation between two similar sections, 3.5.2.d and 3.1.2.2.a. Personnel have been briefed on the differences and a technical specification change will be submitted to reduce confusion.

FACILITY
STATUS
11616

POWER
0 1 3 10

OTHER STATUS
NA

METHOD OF
DISCOVERY
[Z] (31)

DISCOVERY DESCRIPTION (32)
NA

| 9 | 10 |
|----------|------------|
| ACTIVITY | CONTENT |
| RELEASED | OF RELEASE |

AMOUNT OF ACTIVITY
NA

LOCATION OF RELEASE (36)
NA

| PERSONNEL EXPOSURES | |
|---------------------|------|
| NUMBER | TYPE |
| 10 | |
| 11 | |

DESCRIPTION (39)

| | 11 | 12 |
|--------------------|----|-----|
| PERSONNEL INJURIES | | |
| NUMBER | | DES |

13
TION (41)

| 9 | 11 | 12 |
|-------------------------------|-------------|----|
| LOSS OF OR DAMAGE TO FACILITY | | |
| TYPE | DESCRIPTION | |

PUBLICITY
DESCRIPTION (45)

8205110283 820503
PDR ADCK 05000336
S PDR

NRC USE ONLY

NAME OF PREPARER R. W. Bates

PHONE (203) 447-1791

SEP 01 7-920