



April 30, 1982

Log No. K82-707
FILE: RR 2 (NP-32-82-03)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence 82-019
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: April 26, 1982

Enclosed are three copies of Licensee Event Report 82-019 including supplemental information sheets which are being submitted in accordance with Technical Specification 6.9 to provide 14 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray /smq

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/lmr

Enclosure

CC: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 40 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies
2 copies telecopied report

Mr. Walt Rogers
NRC Resident Inspector
Encl: 1 copy

MAY 5 1982

IK 22
5/11