



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

April 27, 1982

DJS Ltr. #82-503

James G. Keppler Regional Administrator
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



Reportable Occurrence Report #82-19/01T-0, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(c), abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

8205110501 820427
PDR ADOCK 05000249
S PDR

MAY 3 1982

IE22