



Certified By

M. A. Perham

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

TELEPHONE
AREA CODE 716 546-2700

January 28, 1982

Mr. Ronald C. Haynes,
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, PA 19406

Subject: LER 82-003/01T, "B" Steam Generator Tube Failure

Dear Mr. Haynes:

As a result of a conversation with Mr. Roy Zimmerman and Mr. Jim Wiggins regarding the failure to notify Region I of a 24 hour notification event, the direction of the Resident Inspector was to submit this letter to provide notification of LER 82-003.

In accordance with Technical Specification 6.9.2.a.3, "abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment", the following is submitted.

On January 25, 1982, Ginna Station experienced a failure of steam generator tubing in the "B" Steam Generator. This event led to a site evacuation and release of radioactive material to the environment. Further information regarding this LER will be submitted with the 14 Day Written Report.

Rochester Gas & Electric Corporation regrets the delay in submitting this 24 hour notification letter.

Bruce A. Snow
Plant Superintendent

xc: J. E. Maier
R. P. Zimmerman NRC Resident Inspector
CAR 1351 File

IER
5/0