



Commonwealth Edison

## DEVIATION REPORT

DVR NO. 12 - 2 - 82 - 16  
STA UNIT YEAR NO.

PART 1 TITLE OF DEVIATION Failure to Take Unit 2 and 3  
Battery Pilot Cell Voltages OCCURRED 3/25/82 1200  
DATE TIME

EM AFFECTED 8300 PLANT STATUS AT TIME OF EVENT 2500 (2) 800 (2) TESTING  
DC Systems MODE U-2 Run U-3 S/D PWR(MWT) 0 (3) LOAD(MWE) 0 (3) YES NO

DESCRIPTION OF EVENT Pilot cell voltage readings were not taken for the Unit 2 or Unit 3

24/48 VDC, 125 VDC or 250 VDC batteries as required by Tech. Spec. Surveillance

Requirement 4.9.B.1.

EQUIPMENT FAILURE 10 CFR50.72 NRC RED PHONE YES NO  
NOTIFICATION MADE YES NO

WORK REQUEST NO. RESPONSIBLE SUPERVISOR Michael Wright DATE 3/25/82

PART 2 OPERATING ENGINEER'S COMMENTS A notation was made on the surveillance procedure stating

that the fluke voltmeter used for voltage reading was broken. This event will be  
reviewed with the shift supervisors to prevent recurrence.

☐ EVENT OF PUBLIC INTEREST

☐ TECH. SPEC. VIOLATION

☐ NON REPORTABLE OCCURRENCE

☐ 14 DAY REPORTABLE/T.S.

☒ 30 DAY REPORTABLE/T.S. 6.6.B.2.c.

☐ ANNUAL/SPECL REPORT REQ'D

A.I.R. #

L.E.R. # 82-10/03L-0

☐ 24-HOUR NRC NOTIFICATION REQ'D

TELEPH Tom Tongue (courtesy) 3/25/82 1300

REGION III DATE TIME

TELEGM/TELECOPY

REGION III DATE TIME

☐ CECO CORPORATE NOTIFICATION MADE

IF ABOVE NOTIFICATION IS PER 10CFR21

☐ 5-DAY WRITTEN REPORT REQ'D PER 10CFR21

TELEPH F. A. Palmer 3/25/82 1457

CECO CORPORATE OFFICER DATE TIME

PRELIMINARY REPORT  
COMPLETED AND REVIEWED

Michael Wright

3/25/82

OPERATING ENGINEER

INVESTIGATED REPORT & RESOLUTION  
ACCEPTED BY STATION REVIEW

Jack Brunner  
4/22/82

Michael Wright  
4-22-82

RESOLUTION APPROVED AND  
AUTHORIZED FOR DISTRIBUTION

86-5176 (FORM 15-52-1) 10-81

8205180-574

STATION SUPERINTENDENT

4/22/82  
DATE

IE22  
11/1