

NEW YORK STATE POWER AUTHORITY R
BOX 215
BUCHANAN NY 10511

western union

Mailgram



4-043688S132003 05/12/82 ICS IPMTZZ CSP PHAB
2 9147348200 MGM TDMT BUCHANAN NY 05-12 0350P EST

NUCLEAR REGULATORY COMMISSION ATTN RONALD C
HAYNES DIRECTOR
REGION 1 OFFICE OF INSPECTION AND ENFORCEMENT
631 PARK AVE
KING OF PRUSSIA PA 19406

THIS IS A CONFIRMATION COPY OF A TELEGRAM ADDRESSED TO YOU
ON APRIL 15, 1982 WITH THE PLANT IN THE COLD SHUTDOWN CONDITION FOR
THE REFUELING OUTAGE PERFORMANCE OF SURVEILLANCE TEST 3PC-R4
(PRESSURIZER PRESSURE CALIBRATION) INDICATED THAT PRESSURE
TRANSMITTERS PT456 PT457 AND PT474 WERE OUT OF SPECIFICATION
NON-CONSERVATIVELY AT A TEST PRESSURE 1800 PSIG. SUBSEQUENT
ENGINEERING ANALYSIS COMPLETED ON MAY 12 DETERMINED THAT UNDER THESE
CONDITIONS THE LOW PRESSURIZER PRESSURE REACTOR TRIP SIGNAL WOULD
OCCUR AT A SYSTEM PRESSURE OF 1797 PSIG WHICH IS BELOW THE LIMIT OF
1800 PSIG SET BY TECHNICAL SPECIFICATION 2.3.1.8.3 RESIDENT AND RC
INSPECTOR T KENNY WAS NOTIFIED AT 1400 HOURS ON MAY 12 1982. THIS
TELEGRAM SERVES THE 24 HOUR NOTIFICATION REQUIRED BY TECHNICAL
SPECIFICATION 6.9.1.7.8.

J C BRONS RESIDENT MGR INDIAN POINT 3 NUCLEAR POWER PLANT (BOX 215
BUCHANAN NY 10511)
BOX 215
BUCHANAN NY 10511

15:53 EST

MGMCOMP

8205200038 820512
PDR ADOCK 05000286
S PDR

IE29
1/0