

RECEIVED
NRC

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

1982 MAY 14 AM 11:03

SCE

REGION V

TELEPHONE
(714) 492-7700

H. B. RAY

STATION MANAGER

May 6, 1982

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Docket No. 50-361

Follow Up to Licensee Event Report No. 82-007
San Onofre Nuclear Generating Station, Unit 2


References: Letter, H. B. Ray (SCE) to R. H. Engelken, dated April 7,
1982 (LER 82-007 attached)

Dear Sir:

This letter is submitted to correct Equipment Tag Number errors contained in our letter submitted to you with LER 82-007 on April 7, 1982. In the subject letter, the area manual switch was identified as tag number (2HS8973); it should have been tag number (2HS5602). The deluge valve was identified as tag number (2HS8973A); it should have been tag number (2HS5602). The manual block valve was identified as tag number (2S230IMU200); it should have been tag number (2S230IMU117).

We apologize for any inconvenience these inadvertent errors may have caused.

Sincerely,



cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission
Office of Management Information and Program Control

Institute of Nuclear Power Operations (INPO)

A. E. Chaffee (USNRC Resident Inspector - San Onofre Unit 2)

IE22
3/10

8205210343 820506
PDR ADOCK 05000361
S PDR