

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

82 MAY 25 AM 11:14  
May 20, 1982

BLRD-50-438/82-08, -439/82-08  
HTRD-50-518/82-05, -519/82-04  
-520/82-05, -521/82-04  
PBRD-50-553/82-04, -554/82-04  
YCRD-50-566/82-03, -567/82-03

U.S. Nuclear Regulatory Commission  
Region II

ATTN: James P. O'Reilly, Regional Administrator  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

BELLFONTE, HARTSVILLE, PHIPPS BEND, AND YELLOW CREEK NUCLEAR PLANTS -  
REPORTABLE DEFICIENCY - FAILURE OF TRANSAMERICA DELAVAL TO PROMPTLY  
CORRECT DEFICIENCIES - BLRD-50-438/82-08, -439/82-08 - HTRD-50-518/82-05,  
-519/82-04, -520/82-05, -521/82-04 - PBRD-50-553/82-04, -554/82-04 -  
YCRD-50-566/82-03, -567/82-03

The subject deficiency was initially reported to R. C. Lewis, NRC-OIE,  
Region II on January 14, 1982 as Audit 81V-47, Deficiency No. 1. The  
final report was submitted on March 19, 1982. As discussed with  
Inspector Ross Butcher on April 29, 1982, TVA was unable to complete  
corrective actions by the April 30, 1982 commitment date as stated in  
our final response. TVA now anticipates completing corrective actions  
by June 30, 1982. We consider 10 CFR Part 21 applicable to this  
nonconformance. If you have any questions, please call Jim Domer at FTS  
358-2725.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
L. M. Mills, Manager  
Nuclear Licensing

cc: Mr. R. C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

8206010216

OFFICIAL COPY

IE 27  
5-110