

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

April 23, 1982

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-27 was to have been submitted by April 23, 1982. This 30 day Reportable Occurrence (per T.S.6.9.1.13) concerns T.S.3.3.3.6, "The accident monitoring instrumentation channels shown in Table 3.3-10 shall be operable", which was violated on March 26, 1982. At this time, all of the required information is not yet available. The complete report will be submitted by May 10, 1982.

Very truly yours,


William O. Parker, Jr.

PBN/jfw

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector
McGuire Nuclear Station

8206010675 S

OFFICIAL COPY

IE 22
5/1/80