

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

May 24, 1982

USNRC REGIONAL
ATLANTA, GEORGIA
02 JUN 2 4 8.33
TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-33 was to have been submitted by May 24, 1982. This 30 day reportable occurrence (per T.S.6.9.1.13) concerns T.S.3.1.1.4, "The Reactor Coolant System lowest operating loop temperature (T_{avg}) shall be greater than or equal to 551°F", which was violated on April 24, 1982. At this time investigation of the incident is not yet complete. The report will be submitted by June 4, 1982.

Very truly yours,


William O. Parker, Jr.

PBN/jfw

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector
McGuire Nuclear Station

OFFICIAL COPY

IE 22
1/0

8206070333 820524
PDR ADOCK 05000369
S PDR