



Carolina Power & Light Company

May 26, 1982

USNRC REGION II
ATLANTA, GEORGIA
82 JUN 2 4 34

FILE: SH N-2/18
ITEM 75

CQAD 82-940

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT
DOCKET NOS. 50-400, 50-401
SHOP WELD DEFICIENCY ON JOSEPH OATES
SUPPLIED HEAT EXCHANGERS
SECOND INTERIM REPORT

Dear Mr. O'Reilly:

On March 24, 1982, the NRC (Mr. C. Julian) was informed that the subject item was considered potentially reportable per the provisions of 10CFR50.55(e) and 10CFR21. The intent of this letter is to inform you that due to difficulties in gaining access for engineering examinations and other pressing priorities, we have not been able to complete our reportability evaluation.


To date, three (3) of the ten (10) (Note: Initial notification incorrectly indicated there were nine (9) vessels) heat exchanger vessels have been examined. CP&L welding engineering personnel will continue to examine the remaining welds to determine the extent of the deficiencies. CP&L plant engineering personnel will determine whether or not these deficiencies are reportable under the provisions of 10CFR50.55(e) and 10CFR21. It is anticipated that the investigation and evaluation of this problem will be completed by June 11, 1982, at which time the NRC will be informed of the results of our evaluation.

Completion of corrective action will depend on the results of the evaluation and extent of rework required. If this item is deemed reportable, the NRC will be so notified and the projected date of completion of corrective action provided through submittal of an interim letter.

May 26, 1982

Thank you for your consideration in this matter.

Yours very truly,

A handwritten signature in dark ink, appearing to read "N. J. Chiangi", with a long horizontal stroke extending to the right.

N. J. Chiangi - Manager
Engineering & Construction
Quality Assurance/Quality Control

NJC/gea (206)

cc: Mr. G. Maxwell
Mr. V. Stello (2)