



VERMONT YANKEE NUCLEAR POWER CORPORATION

SEVENTY SEVEN GROVE STREET
RUTLAND, VERMONT 05701

2.C.2.1
FVY 82-65

REPLY TO:

ENGINEERING OFFICE

1671 WORCESTER ROAD
FRAMINGHAM, MASSACHUSETTS 01701
TELEPHONE 617-872-8100

June 4, 1982

U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Attention: Office of Nuclear Reactor Regulation
Mr. Domenic B. Vassallo, Chief
Operating Reactors Branch #2
Division of Licensing

References: a) License No. DPR-28 (Docket No. 50-271)
b) Letter, VYNPC to USNRC, FVY 82-61, dated 5/27/82
c) Letter, USNRC to VYNPC, dated 3/17/82
d) Letter, VYNPC to USNRC, FVY 82-1, dated 1/5/82
e) Letter, VYNPC to USNRC, FVY 81-110, dated 8/5/81
f) Letter, VYNPC to USNRC, FVY 81-69, dated 4/17/81
g) Letter, VYNPC to USNRC, WVY 80-170, dated 12/15/80

Dear Sir:

Subject: Post-TMI Requirements

Reference (b) requested Vermont Yankee to submit the completion status of certain NUREG-0737 items. We submitted the status via Reference (c); however, we inadvertently omitted information regarding the status of three of those items. This information is attached.

We trust that this information is acceptable; however, should you have any further questions, please contact us.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

Earl W. Jackson
Earl W. Jackson
Manager of Operations

EWJ/dm

AdA

8206100127 820604
PDR ADOCK 05000271
PDR

STATE OF VERMONT)
)ss
WINDHAM COUNTY)

Then personally appeared before me, E.W. Jackson, who, being duly sworn, did state that he is Manager of Operations of Vermont Yankee Nuclear Power Corporation, that he is duly authorized to execute and file the foregoing request in the name and on the behalf of Vermont Yankee Nuclear Power Corporation and that the statements therein are true to the best of his knowledge and belief.



Diane M. McCue Notary Public
My commission Expires February 10, 1983



ENCLOSURE 1

Item II.K.3.22 - RCIC Section Transfer

References (d) and (g)

The implementation of this item, as discussed in the above References, was complete as of November 25, 1981.

Item II.K.3.24 - Space Cooling for HPCI/RCIC

References (d) and (g)

As discussed in the above References, no modifications were necessary.

Item III.K.3.27 - Common Reference Level

References (e), (f), and (g)

The implementation of this item, as discussed in the above References, was complete prior to the startup following the 1981 refueling outage.