

# DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

April 1, 1982

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303


Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369



Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/82-20. This report concerns T.S.3.3.3.7, "As a minimum, the fire detection instrumentation for each fire detection zone shown in Table 3.3-11 shall be operable". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

  
William O. Parker, Jr.

PBN/jfw  
Attachment

cc: Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Records Center  
Institute of Nuclear Power Operations  
1820 Water Place  
Atlanta, Georgia 30339

Mr. P. R. Bemis  
Senior Resident Inspector-NRC  
McGuire Nuclear Station

OFFICIAL COPY

8204160548 820401  
PDR ADOCK 05000369  
S PDR

IE 22  
1/1